



# MOZAMBIQUE - Beira City

## Macurungo - Structural Damage by Construction Typology - As of 26 March

For Humanitarian Purposes Only  
Production date: 30 April 2019



Data sources:  
Damage sites - UNOSAT-REACH  
Beira Bairros - INGC  
Bairros Delineation - REACH  
Administrative Boundaries (0-3) - OCHA  
Satellite Imagery: WorldView-2 from 26 March 2019  
Copyright: ©DigitalGlobe 2019  
Source: US Dept of State Humanitarian Information Unit, NextView License



Coordinate System: GCS WGS 1984  
File: MOZ\_Map\_Cycloneldai\_Beira\_DamageByType\_Macurungo\_30APR2019  
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.